

Mobile Video Recorder

Version: V5.6.1 Release Note

Firmware Basic Information

AE-MD5043

AE-MD5043_EN_5.6.1_20220711

AE-MN5043

AE-MN5043_EN_5.6.1_20220711

AE-MH0408

AE-MH0408_EN_5.6.1_20220711



Reason of Upgrade

Fix minor bug

1. Bug fixed

- 1. Solve the issue that the network priority working abnormally when there are more than two network cards enabled simultaneously of MVR (including 4G/WIFI/ETH0/ETH1), for the default gateway will be switched continuously between the enabled cards;
- 2. Fix the problem that the encrypted video downloading failed on the web service;

Related product list

| | AE-MD5043(1T)(O-STD) |
|--|----------------------------|
| | AE-MD5043(O-STD) |
| | AE-MN5043(1T)(M12)(O-STD) |
| | AE-MN5043(RJ45)(O-STD) |
| | AE-MN5043(M12)(O-STD) |
| | AE-MN5043(1T)(RJ45)(O-STD) |
| | AE-MH0408(RJ45)(O-STD) |
| | AE-MH0408(1T)(RJ45)(O-STD) |

Customer Impact and Recommended Action

This new firmware upgrade is to improve product performance, and will take effect automatically after upgrading from previous versions. We'd like to inform you the above



changes. Also, we are sorry for any possible inconvenience of use-habit changes caused by this action.

Note:

- Hikvision has all rights to alter, modify and cancel this notice.
- Hikvision doesn't give any guarantee for old models' stock.
- Hikvision is not liable for any typing or printing errors.
- For special model's change details, please contact our local technical support team.