

KD8 (-B) Modular Door Station
(Main Modular)
Version: V2.2.58_build220929
Release Note
(2022-09-30)

1. Firmware Basic Information

Firmware Basic Information	Firmware Version	V2.2.58_220929
	Device Type	DS-KD8003-IME1(B) DS-KD8003-IME1(B)/Surface DS-KD8003-IME1(B)/Flush DS-KD8003-IME1(B)/S DS-KD8003-IME1(B)/NS DS-KD8003Y-IME2 DS-KD8003Y-IME2/S DS-KD8003Y-IME2/NS
	Device Type (Kits)	DS-KIS602(B) DS-KIS702Y

Fix:

Fixed a large area of the left FOV being obscured due to lens distortion.

KD8 (-B) Modular Door Station (Main Modular)

Version: V2.2.58_build220725

Release Note (2022-08-02)

1. Firmware Basic Information

Firmware Basic Information	Firmware Version	V2.2.58_220725
	Device Type	(2022-08-02): DS-KD8003-IME1(B) DS-KD8003-IME1(B)/Surface DS-KD8003-IME1(B)/Flush (2022-08-23): DS-KD8003-IME1(B)/S DS-KD8003-IME1(B)/N/S
	Device Type (Kits)	(2022-08-02): DS-KIS602(B)

Notes:

This is a newly released hardware version, and the software which is inherited all the functions of the previous version of DS-KD8003 series.

1.1 Recommended Firmware

It is recommended to use the following devices and version together, because they can cooperate and work normally after the docking test.

Test resource	Device type	Version
New version	KD8003-IME1	V2.2.56_220424
	DS-KD-TDM	V1.0.1_220424
Door Station	KD9403	V2.2.37_211125
	KV6113, KV8X13	V2.2.52_211104
	DS-KD-DIS	V1.0.4_build211111
	DS-KD-KK, DS-KD-KP	V1.1.1_build210318

	DS-KD-M	V2.0.0_build210223
Indoor Station	DS-KH6320-LE1	V1.4.60_build211209
	KH6320-WTE1	V2.1.34_build211118
	KH9310	V2.1.28_build210803
Main Station	KM9503	V1.0.34_build220212
IVMS-4200	IVMS-4200 Client	V3.5.0.101_build20220418

Notes:

Test records only contain the cases for normal devices and do not represent all the scenarios and all the functions.

2. New

2.1 Support the Web Client to login:



2.2 Support European Portuguese and Slovak, and support language switching without restart.

Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051,
China
Tel: +86-571-8807-5998
FAX: +86-571-8993-5635
Email: overseabusiness@hikvision.com