

Title:	RN KB8112	Version:	v1.4.6	Date:	061818
Product:	Door Station	Build:	180320	Page:	1 of 2
Action Required:	None, Information Only				

■ General Information

■ Fixes

- **Live view no longer fails due to “sensor type mismatch”**
- **Hik-Connect no longer receives motion detection push notifications when the notify surveillance center check box is enabled in iVMS-4200 (Ver 1.4.6_180211)**
- **Product name in system info is now encrypted as DS-KB8112-IM/US (Ver 1.4.6_171221)**
- **Hik-Connect no longer automatically drops call from DS-KB8112-IM when the latter is in doorphone mode (Ver 1.4.6_171129)**

■ New Features

- **Optimized Voice Prompt for troubleshooting**

When KB8112 is not connected to a Hik-Connect cloud account or any indoor station, voice prompt: “Indoor Station or Cloud Account Not Found” is produced.

When no one answers to the call, voice prompt: “Not available” is given.

- **IR LED switches on or off automatically based on changing light conditions.**
- **Alarms are now forward to multiple platforms simultaneously, such as iVMS-4200 and NVR.**
- **While DS-KB8112-IM is in either standard or doorphone mode, alarms are sent to NVR or iVMS4200**
- **Can now connect to a doorbell chime when choosing alarm out mode as custom (sacrifices alarm out feature) (Ver 1.4.6_171116)**
- **The call button now triggers NO/NC/COM relay when pushed (Ver 1.4.6_171116)**
- **Doorbell sound effects added when pressing the call button (Ver 1.4.6_171116)**