

## Network Camera Firmware

Version: V5.6.11\_200901

### Release Notes

#### Reason of Upgrade

Upgrade for supporting new features and better performance.

#### New features

1. Now can enable 'Remove Duplicated License Plates' and set the interval time of it.

☒ Remove Duplicated License Plates

Time Interval

4

minute(s)

 Save

2. The extra time delay of Alarm Output has been removed (previously was 5s).

3. Support manual gain adjustment under automatic mode of day and night switching (previously was not supported while in auto mode).

#### ^ Day/Night Switch

Day/Night Switch

Auto



#### ^ Exposure Settings

Iris Mode

Manual



Exposure Time

1/1000



▼ Exposure

4. Now support optional Detection mode of Vehicle Priority and License Plate & Vehicle under Entrance/Exit mode.

Select Mode

Entrance/Exit



Detection mode

Vehicle Priority

License Plate & Vehicle

☒ Remove Duplicated License Plates

Time Interval

4



minute(s)

 Save

5. Now the device supports Hikvision security guidelines 2.0.

6. “When the HLC is on, Day & Night switch can’t work normally” has been fixed.

7. Now the device will not easily lose focus after the Day & Night switch.


8. Fix the problem that Road Traffic – Picture - FTP Picture Name – Custom – Capture Time is firmly selected.

**FTP Picture Name**

☐ Default
 ☒ Custom

☒ Alarm Type
 ☐ Camera Name
 ☐ Capture Time
 ☒ Plate No.

Type	Sorting
Plate No.	<input type="button" value="↑"/> <input type="button" value="↓"/>
Alarm Type	<input type="button" value="↑"/> <input type="button" value="↓"/>


 Save

9. Fix the export failure problem in Picture interface.

**HIKVISION®**

Live View
 Playback
 **Picture**
 Configuration

**Download by File**

Search Conditions	File List	
	No.	File Name
File Type <div>Vehicle Detection</div>		
Plate No. <input type="text"/>		
Start Time <div>2020-06-29 00:00:00</div>		
End Time <div>2020-06-29 23:59:59</div>		
<div>  Search                             </div>		
<div>Export</div>		

10. Fix license plate number disorder with special characters in excel table of export.

11. Now the high frame selection (50fps, 60fps) has been removed.



First Choice for Security Professionals

## Customer Impact and Recommended Action

This update refers to function/compatibility improvement and will take effect automatically after the Date of Change. We are very sorry for any inconvenience of use-habit changes caused by this action. For any questions and request for this firmware, please contact our local technical support team.

### Remarks:

- Hikvision reserves the right to change, alter or withdraw the above notification without prior notice.
- Product design and specifications are subject to change without prior notice.
- The Hikvision firmware may contain defects or errors known as errata which may cause the product to deviate from published specifications. Current characterized errata are available on request.
- Hikvision is not liable for any typing or printing errors.

Hikvision Digital Technology CO., Ltd.  
No. 555 Qianmo Road, Binjiang District, Hangzhou 310051, China  
Tel: +86-571-8807-5998  
FAX: +86-571-8993-5635  
Email: [overseabusiness@hikvision.com](mailto:overseabusiness@hikvision.com)

Supported Product List
DS-2CD7A26G0/P-IZHS(2.8-12mm)
DS-2CD7A26G0/P-IZHS(8-32mm)