



01/2013 Product News.....	2
DVR/NVR/HDVR/DVS.....	3
1. China GUI Firmware V2.3.0_130108 Released, USA GUI Firmware V2.3.0_130130 Ready for Field Trail	3
CAMERAS.....	4
1. New IP Camera Ready for Field Trial	4
2. Release DM365 IP Camera Firmware V4.1.0 Build 130111	5
3. IP Camera DS-2CD7153-E Compatible Issue with Cisco PoE Switch.....	6
4. Camera DS-2CC5173N-VP Manufactured in 06/2011 and 07/2011 Loose Lens Issue	7
SOFTWARE	8
1. iVMS-4200 Client Software V1.02.07.50 Ready for Field Trail	8
2. iVMS-4200 PCNVR Software V1.02.00.03 Ready for Field Trail	8
DOCUMENT.....	9
1. Camera Network Port List Technical Bulletin	9
2. Update HDD Compatible List	9



01/2013 Product News



DVR/NVR/HDVR/DVS

1. China GUI Firmware V2.3.0_130108 Released, USA GUI Firmware V2.3.0_130130 Ready for Field Trail

Compatible Model:

DS-7608NI-ST, DS-7608NI-SP, DS-7616NI-ST, DS-7616NI-SP

DS-7708NI-ST, DS-7708NI-SP, DS-7716NI-ST, DS-7716NI-SP, DS-7732NI-ST, DS-7732NI-SP

DS-8508NI-ST, DS-8516NI-ST, DS-8532NI-ST, DS-8608NI-ST, DS-8616NI-ST, DS-8632NI-ST,

DS-8664NI-ST

DS-9508NI-RT, DS-9508NI-ST, DS-9516NI-RT, DS-9516NI-ST, DS-9532N-RT, DS-9532N-ST

DS-9608NI-RT, DS-9608NI-ST, DS-9616NI-RT, DS-9616NI-ST, DS-9616NI-XT, DS-9632NI-ST

DS-9632NI-XT, DS-9632NI-RT, DS-9664N-ST, DS-9664NI-XT, DS-9664NI-RT

DS-8004HFI-ST, DS-8008HFI-ST, DS-8016HFI-ST, DS-8104HFI-ST, DS-8108HFI-ST,

DS-8116HFI-ST

DS-9004HFI-ST, DS-9008HFI-ST, DS-9016HFI-ST, DS-9104HFI-ST, DS-9108HFI-ST,

DS-9116HFI-ST



CAMERAS

1. New IP Camera Ready for Field Trial

Model	Brief Description
DS-2CD8255F-EIZ	Outdoor Bulletin, 1080P, DWDR, IR, Motorized Zoom, 12VDC/PoE
DS-2CD8254FWD-EIZ	Outdoor Bulletin, 3MP, WDR, IR, Motorized Zoom, 12VDC/PoE
DS-2CD8283F-EIZ	Outdoor Bulletin, 5MP, IR, Motorized Zoom, 12VDC/PoE
DS-2CD764FWD-EZ	Indoor Dome, 1.3MP, WDR, Elect. D/N, Motorized Zoom, 12VDC/PoE
DS-2CD764FWD-EIZ	Indoor Dome, 1.3MP, WDR, IR, Motorized Zoom, 12VDC/PoE
DS-2CD755F-EZ	Indoor Dome, 1080P, DWDR, Elect. D/N, Motorized Zoom, 12VDC/PoE



2. Release DM365 IP Camera Firmware V4.1.0 Build 130111

Compatible Models:

DS-2CD833F-E, DS-2CD893NF-E, DS-2CD893NFWD-E, DS-2CD863NF-E, DS-2CD864FWD-E,

DS-2CD864F-E, DS-2CD853F-E, DS-2CD855F-E, DS-2CD854F-E, DS-2CD854FWD-E,

DS-2CD883F-E

DS-2CD733F-E(I)(Z), DS-2CD793NF-E(I)(Z), DS-2CD793NFWD-E(I)(Z), DS-2CD763NF-E(I)(Z),

DS-2CD764FWD-E(I)(Z), DS-2CD764F-E(I)(Z), DS-2CD753F-E(I)(Z), DS-2CD755F-E(I)(Z),

DS-2CD754FWD-E(I)(B), DS-2CD754F-E(I), DS-2CD754FWD-E(I)Z, DS-2CD783F-E(I)(Z),

DS-2CD7133-E, DS-2CD7164-E, DS-2CD7153-E

DS-2CD8133F-E(I)(B), DS-2CD8153F-E(I)(B)

DS-2CD8233F-E(I)(Z), DS-2CD8264FWD-E(I)(Z), DS-2CD8264F-E(I)(Z), DS-2CD8253F-E(I)(S),

DS-2CD8253F-E(I)(Z), DS-2CD8255F-E(I)(Z), DS-2CD8254F-E(I)(S), DS-2CD8254FWD-E(I)(Z),

DS-2CD8283F-E(I)(Z)

DS-2CD7233F-E(I)Z(H), DS-2CD7293NF-E(I)Z(H), DS-2CD7293NFWD-E(I)Z(H),

DS-2CD7263NF-E(I)Z(H), DS-2CD7264FWD-E(I)Z(H), DS-2CD7255F-E(I)Z(H),

DS-2CD7254FWD-E(I)Z(H), DS-2CD7283F-E(I)Z(H)

DS-2CD8464F-E(I)(W), DS-2CD8433F-E(I)(W)

DS-2CD864F-EI3, DS-2CD855F-EI3, DS-2CD855F-EI5, DS-2CD783F-EP(B), DS-2CD7353F-EI



3. IP Camera DS-2CD7153-E Compatible Issue with Cisco PoE Switch

As customer's feedback some of DS-2CD7153-E cannot be start up by Cisco PoE switch, but can be start up by other brand (such as NetGear, Linksys) PoE switch

Our IP cameras are fully compliant with 802.3af standard. We sold several hundred thousand of 7153/7164 cameras, only got very rare PoE switch compatible issue.

There is handshake time range between PD and PSD. We believed that Cisco PoE switch is more strict than other brand PoE switch (such as NetGear, Linksys), so our camera cannot be start up by Cisco PoE switch, but still can be start up by other brand PoE switch.

Our USA team and R&D are doing more investigation. Current solution is changing a resistance on PCB to short handshake time to resolve Cisco PoE switch compatible issue.



4. Camera DS-2CC5173N-VP Manufactured in 06/2011 and 07/2011 Loose Lens Issue

We found that part of DS-2CC5173N-VP inventory (manufactured in 06/2011, 07/2011) have lens loose issue. We hold these cameras shipment, and are checking with HQ the solution.

Camera which is manufactured from 08/2012 do NOT have this issue, we will ship these camera to the customers if there is order.



SOFTWARE

1. iVMS-4200 Client Software V1.02.07.50 Ready for Field Trail

Update:

Replaced splash screen with "Intelligent", the old one is "Intelligence".

Fixed the issue of motion detection setting failure on NVR.

Fixed the issue of missing of IP channel of Hybrid DVR when configure new user permission on remotely configuration.

Added hint "When using event recording with resolution changes, this conversion will result in multiple video clips!" on recorded file format convert page.

Changed default installation settings, only install Client as default.

2. iVMS-4200 PCNVR Software V1.02.00.03 Ready for Field Trail

<http://www.hikvision.com/en/download.asp>

Brief description:

iVMS-4200 PCNVR is used to replace iVMS-2000 PCNVR. It has the similar GUI as iVMS-4200 client software, and is fully compatible with iVMS-4200 client software for remote access.



DOCUMENT

1. Camera Network Port List Technical Bulletin

http://www.hikvision.com/En/US/support_more.asp?id=228

2. Update HDD Compatible List

http://www.hikvision.com/En/support_more.asp?id=201