

Firmware Release Notes

Firmware version DZR20210507001_01_H11_EN_STD_V2.1.35_210507 works with DS-KV8113-WME1 only. This firmware has the following update:

- Can be added to HikConnect directly without indoor station involvement

Please note the following limitations

- Only 1 phone will ring even if multiple users share the same unit across HikConnect
- Unit needs to be defaulted after this firmware upgrade, otherwise you cannot enable HikConnect option on device web page
- There is no QR code for users to scan. You need to manually type in the serial number to proceed the adding. A laptop is needed, and you need to go to system -> Network -> Advanced -> Platform Access to enable HikConnect and get verification code.