

<b>Title:</b>	RN TurboHD DVR Firmware Release Notes	<b>Version:</b>	v3.1.121	<b>Date:</b>	031417
<b>Product:</b>	DS-72xxHUI-Kx and DS-72xxHQI-Kx Series TurboHD DVRs	<b>Build:</b>		<b>Page:</b>	1 of 1
<b>Action Required:</b>	None, Information Only				

## ■ Summary

Release notes for DS-xxxxHGHI-SH and DS-xxxxHQHI-SH TurboHD DVRs.

## ■ Version: v3.1.121\_170407 (BOM version) Date: 7 April 2017

### • Models

- DS-7208HGHI-SH-1TB
- DS-7216HGHI-SH-1TB
- DS-9004HQHI-SH-4TB
- DS-9008HQHI-SH-8TB
- DS-9016HQHI-SH-16TB
- DS-9016HQHI-SH-2TB
- DS-9016HQHI-SH-4TB
- DS-9016HQHI-SH-8TB

### • Updates

- Changed FW version number to distinguish from US baseline. 3.4.2 = 3.4.2xx, 3.3.6 = 3.3.6xx, 3.1.12 – 3.1.12x,
- Removed HiDDNS and IP server;
- HIK-Connect updated, same as US baseline.
- Default disable UPnP and HIK-Connect.
- Changed Advanced security mode mechanism: If user enables HIK-Connect and sets ASM mode to high, HIK-Connect status would remain.
- I-View Now modification
  - Removed UPnP report password, same as USbaseline
  - Fixed Email Reporting with SSL issue